





















-  X2
-  X1
-  X3
-  X2
-  X1
-  X3
-  X2
-  0
-  X2
-  X1
-  X2
-  X2
-  X3
-  X2
-  X4
-  X3
-  X6
-  X2
-  X4

Advance Warning Sign Details (T)



Additional Sign 1



Additional Sign 2



Shippon
Barrow Road Junction
Carriageway Repairs

